



## **Opacity**

Opacity is a measure of the ability of paper to obstruct the passage of light through the sheet, thereby obstructing the view of printing or objects on the opposite side of the paper.

Opacity is influenced by basis weight and filler or coating materials that are added to the sheet.